

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**NE Corner**

1

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**North Façade**

2

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**NW Corner**

3

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**East Façade and Windows in Gable End**

4



**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**SW Corner**

5

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**South Facade**

6

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Small AC Unit to be Replaced with Window**

7

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Detail AC Unit**

8

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



Looking East at East Column at Front Porch  
and  
Lower Pier East of Front Steps at Front Porch

9

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



Pier East of Front Steps

10



**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Porch Beam Above East Pier Offers No Evidence of Previously Existing Column**

11

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Interaction of Easternmost Porch Column**

12

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Pier West of Front Steps**

13

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Looking West at West Column at Front Porch  
and  
Lower Pier West of Front Steps at Front Porch**

14

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Interaction of West Column with Beam of Front Porch**

15

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Detail of Front Porch, Piers, and Columns**

16



**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Window and Door to Exchange Locations**

17

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**SW Corner**

18

**HPCA-21-00005**

**530 NW 20<sup>th</sup> Street**



**Trim and Window Details**