

HPCA-22-00123

108 NW 15th



East Side of Property

1

HPCA-22-00123

108 NW 15th



NE Corner; Windows of East Elevation

2

HPCA-22-00123

108 NW 15th



SE Corner; Windows of East Elevation

3

HPCA-22-00123

108 NW 15th



NE Corner

4

HPCA-22-00123

108 NW 15th



North Façade

5

HPCA-22-00123

108 NW 15th



NW Corner

6

HPCA-22-00123

108 NW 15th



NW Corner Second Level; Windows of West Elevation

7

HPCA-22-00123

108 NW 15th



West Side Windows

8

HPCA-22-00123

108 NW 15th



NW Corner Second Level

9

HPCA-22-00123

108 NW 15th



South Side (Rear) Looking East

10

HPCA-22-00123

108 NW 15th



SW Corner Looking North

11

HPCA-22-00123

108 NW 15th



Steps Leading to Front Entry at North Elevation; Note Failing Slope or Terrace

12

HPCA-22-00123

108 NW 15th



Front Entrance with Balcony Above; Looking SE

13

HPCA-22-00123

108 NW 15th



Sidewalk Leading to Front Entrance and Erosion

14

HPCA-22-00123

108 NW 15th



Front Entrance First Floor, North Elevation; Boarded Windows and Sidelights

15

HPCA-22-00123

108 NW 15th



East Side of Front Entrance with Boarded Windows and Sidelights

16

HPCA-22-00123

108 NW 15th



Second Level Balcony with Doors and Windows Boarded

17

HPCA-22-00123

108 NW 15th



Second Level Entrance East Side Railing Detail

18

HPCA-22-00123

108 NW 15th



Second Level Entrance West Side Soffit Detail

19

HPCA-22-00123

108 NW 15th



Second Level North Side Window Detail

20

HPCA-22-00123

108 NW 15th



Front Entrance

21

HPCA-22-00123

108 NW 15th



Front Entrance Ceiling

22

HPCA-22-00123

108 NW 15th



North Side Eaves