

HPCA-19-00085

705 NW 27<sup>th</sup> Street

Columns look the same , no broken brick or exploded faces. Sealant seems to be doing its job;)  
[toddharlin@protonmail.com](mailto:toddharlin@protonmail.com)

