

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**South Elevation**

1

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**East View from Street**

2

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**West Elevation**

3

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**West View from Street**

4



**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**East Gable and Windows for Replacement Beneath and Beyond**

5

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**East Gable and Windows for Replacement**

6

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**First Floor East Gable**

7

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**East Side – Northernmost Windows for Replacement**

8



**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**Upper NE Windows**

9

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**Lower NE Windows Similar to NW Windows**

10

**HPCA-20-00171**

**433 NW 28<sup>th</sup> Street**



**North Elevation – Replace All Windows**

11



12